



Accommodation in Exeter

Maintenance Response Times

Please note that these are based on the time the fault is received by the Maintenance

Service Helpdesk.

1-4 Hours Emergency	1 Working Day	Within 5 Working Days Routine	Within 30 Working Days or by agreed date
Immediate danger	Communal doors -	Defective air	Replace sanitary
to personal safety	lock faults or break	conditioning units	fittings
	in	and ventilation	
		fans	
Serious damage to	Bedroom doors -	Unblock toilet or	Tiling repairs to shower
building fabric or	lock faults or break	urinal (if this is	and bathroom areas
equipment	in	not the only	
		facility locally	
		available)	
Bomb warnings	Secure and protect	Replace or repair	Fence repairs
	broken windows	door closers	
	(may exclude		
	replacement of		
	glass)		

Repairs to light	Replacement of	Joinery repairs
fittings or replace	glass to windows,	
light bulbs, where	doors, and	
only one light	partitions	
within the room	(Where access is	
and causing a	limited this may	
safety hazard	be at an agreed	
	date)	
Unblock toilets or	Plumbing repairs	Repairs to window
urinal (if this is the		frames
only facility locally		
available)		
Clear main	Removal of	Repairs requiring
drainage	graffiti	special parts
blockages		
T		
. , .		General roof repairs
C		that are not urgent
frip hazard		
	of the building	
Temporary repair	Laundrette	Repairs to roof gutters
. , .		and pipes
Faults in en-suite	Loss of heating	Minor repairs to
facilities or shared	(temporary	building fabric
shower		
	light bulbs, where only one light within the room and causing a safety hazard Unblock toilets or urinal (if this is the only facility locally available) Clear main drainage blockages Clear main drainage blockages Temporary repair to flooring that is a trip hazard Temporary repair to carpet that is a trip hazard	fittings or replace light bulbs, where only one light within the room and causing a safety hazard Unblock toilets or urinal (if this is the only facility locally available) Clear main drainage blockages Temporary repair to flooring that is a trip hazard Morks necessary to flooring that is a trip hazard Faults in en-suite facilities or shared facilities or shared (Morks of heating facilities or shared (temporary repair Laundrette blockages Clear main trip hazard facilities or shared (temporary repair Laundrette Loss of heating (temporary repair Laundrette Loss of heating (temporary repair Laundrette Loss of heating (temporary repair Laundrette

	• •	
	provision	
	provided)	
Oven and hob	Commencement	Repair or replacement
	treatment of	of flooring that is not a
	other pest	trip hazard
	infestations	
Loss of hot		Repair or replacement
water/electric		of carpets that is not a
power in		trip hazard
bedroom/kitchen		
Adjustment to		
temperature of		
heating or hot		
water		
Firefighting		
equipment		
Severe pest		
infestations		

Visit the Accommodation website: **<u>exeter.ac.uk/accommodation</u>**